

Avigilon Access Control Manager Software 5.2 Release Notes

Copyright 2014 Avigilon

Version 5.2.0 – Released Tuesday July 29th, 2014

Avigilon Access Control Manager Enterprise Appliance File

- 5.2-upgrade

Avigilon Access Control Manager Virtual Files

- ACM_VM_5.2-disk1.vmdk
- ACM VM 5.2.mf
- ACM VM 5.2.ovf

New Features

- Easy to Use Door Event Scheduler
- Improved Small Screen Support
- Avigilon Video Viewer Updates
- Enhanced Safari Browser Support
- Maximum Number of Tokens Per Identity
- ACM Professional Appliance
- Configurable Private System Warning on Login Page
- Support for Mercury M5-2K subpanel
- Enhanced ACC/ACM Integration

Changes

Fixed Issues

- When setting the time on the appliance page, the page must be refreshed to update the clock
- Unable to modify custom reports in grid view
- ACM/ACC integration time zone issue caused the wrong time to be sent from the event viewer to the video window
- ACM appliance sends false start up warning messages
- Viewing a camera from the Search tab in Firefox and IE resulted in the time-stamp showing “NaN”
- When editing an existing door, selecting and de-selecting a Panel caused a duplicated sub-panel to be populated
- Creating a new door without a name caused an error
- Attempting to view video from a camera assigned to an input caused an error
- “Destroy Batch” button had an inconsistent appearance
- SCP Backup/Restore backup had no way to specify a port other than port 22
- Deleting a local event for an output point or subpanel on the Panel Events tab caused an error
- Deleting a token used in a Global Linkage did not remove the token reference from the Linkage
- Leftover/stale PID file references to Thin caused “appliance appears to be starting up...” messages
- Clicking “1 free pass” button on Identity Tokens tab generated an error

- Exacq: cameras configured for 24x7 motion masking by default were not honored
- Deleting a device used in a Global Linkage did not remove the device reference from the Linkage
- Corrected several Event Report grid view issues
- Javascript caused page reload
- Preview run of CSV collaboration with date errors caused an error
- The Identity Summary Report with a deleted Role reference caused an error
- Clicking the +Camera button in the Search sub tab returned a fatal error
- Deleting the panel a door is assigned to and reassigning the door to new panel did not automatically download the expected access levels
- When changing the service port on an appliance, monitoring did not work until the appliance was rebooted
- Identity Destroy Batch did not function
- With Chrome browser, clicking the FF/Rew buttons in the ACC and Exacq integrations resulted in the browser becoming non-responsive

Firmware Included

Panel Firmware

- EP1501-VER-1-17-6.crc
- EP1501-VER-1-18-8.crc
- EP1502-VER-1-17-6.crc
- EP1502-VER-1-18-8.crc
- EP2500-VER-1-17-6.crc
- EP2500-VER-1-18-8.crc
- M5IC-VER-1-18-1.crc
- M5IC-VER-1-18-8.crc
- Scp2-AES-VER-3-120.crc
- Scp2-VER-3-120.crc
- ScpC-AES-VER-3-120.crc
- ScpC-VER-3-120.crc
- ScpE-AES-VER-3-120.crc
- ScpE-VER-3-120.crc

Sub-Panel Firmware

- MR16in-APPL-VER-1-31-1.aax
- MR16out-APPL-VER-1-31-1.aax
- MR50-APPL-VER-1-51-0.aax
- MR51e-APPL-VER-1-4-3.aax
- MR51e-APPL-VER-1-4-8.aax
- MR51e-LOAD-VER-1-1-11.aax
- MR51e-LOAD-VER-1-1-9.aax
- MR52-APPL-VER-1-51-0.aax
- MR52-SERIES1-VER-1-11.aax

