MOTOROLA SOLUTIONS

Mercury Security v1.30.3.0668 LP Controllers Firmware Note

Monday, June 13, 2022

HID Global was recently informed of cybersecurity vulnerabilities within firmware running on all Mercury LP and EP4502 Intelligent Controllers. HID Global addressed all issues reported and validated fixes with this new firmware.

For any further support, please reach out to your local sales representative.

Mercury Security v1.30.3.0668 is compatible with ACM 6.30 and newer.