

Avigilon H6SL Camera Line Firmware Release Notes

Version 4.66.0.26 – Released September 7, 2023

New Features

- Supported added for 1/10,000s & 1/30,000s exposure levels
- “No Smart Analytics” mode has been renamed to “No Video Analytics”

Issues Fixed

- Resolves internal manufacturing issues
- Resolves an issue that can potentially cause incorrect URL redirections
- Resolves an issue that can potentially cause ACC to fail to register analytic rule clearing/reset to default values until the camera is dis/reconnected or rebooted
- Resolves an issue that can potentially cause the RTSP stream to result in an error when the edge rotation value is changed while the camera is tiling
- Resolves an issue that potentially prevents analytics events from displaying properly on ACC when the camera is rotated 90 degrees

Version 4.60.0.24 – Released May 30, 2023

New Features

- Image rotation is now supported through the WebUI, refer to the user guide for detailed instructions on implementing this feature
- A new option titled “No Smart Analytics” is available through the WebUI that allows the disabling of Smart Analytics functions (basic analytics will not be disabled)
- ONVIF Profile M is now supported

Issues Fixed

- Resolves internal manufacturing issues
- Resolves issues that may be caused by using the new image rotation feature through WebUI in conjunction with image rotation through ACC
- Resolves an issue that could potentially cause issues when loading the WebUI on Mac-based Safari and Google Chrome browsers

Version 4.46.0.24 – Released Nov 15, 2022

Issues Fixed

- Fixes an issue that can cause the camera not to adjust to Daylight Savings Time correctly when set to the IST/IDT time zone
- Fixes an issue where a temporary network disruption to ACC or the NTP service may result in cameras not streaming to ACC, even when the network connection is restored
- Fixes internal manufacturing issues

Version 4.46.0.20 – Released Oct 11, 2022

- Initial firmware release for H6SL Camera Line