

# Avigilon H5A Multisensor Camera Line Firmware Release Notes

## Version 4.66.0.26 – Released September 15, 2023

### New Features

- “No Smart Analytics” mode has been renamed to “No Video Analytics”
- Support added for 1/10,000s & 1/30,000s exposure levels

### Issues Fixed

- Resolves internal manufacturing issues
- Resolves an issue that can potentially cause incorrect URL redirections
- Resolves an issue that can potentially cause the RTSP stream to result in an error when the edge rotation value is changed while the camera is tiling
- Resolves an issue that potentially prevents analytics events from displaying properly on ACC when the image stream is rotated from the WebUI

## Version 4.56.0.36 – Released June 26, 2023

### New Features

- Removable privacy (blur) zones can be applied on the secondary, tertiary and web streams without affecting the primary stream

### Issues Fixed

- Fixes an imaging issue that can potentially cause oscillating changes in image brightness and distorted privacy zones when the lens distortion correction (LDC) feature is enabled
- Resolves internal manufacturing issues